

Mud pump bearings

<!--StartFragment -->

<!--StartFragment -->

Power End:

Fabricated steel frame construction

One-piece forged steel construction crankshaft, connecting rods and pinion shaft

Adapability to a variety of drive arrangements on either side or both sides

Premium roller bearings to enhance smooth performance and efficiency

Pressurized lubrication system standard on 14-P-220 model

Fluid End:

Two-piece modular cylinder design is completely interchangeable between modules
screw-type valve covers which facilitate quick removal and installation are standard

Suction manifold can be equipped with front or side inlet connections

Discharge piping connects from either side

Piston and liner chambers are easily accessible and fully open

Two-piece piston rod construction allows removal of piston without disturbing liner

Easy-to-operate clamps give positive locking for liners and piston rod assemblies

Spray system cools and lubricates piston and liner surfaces

| | | | | |
|--------------------------------------|----------|---------|--------------|----------|
| ZT15000 | ZB-6751 | 12BA18 | ZT-10003 | 10-6061 |
| ZB10236 | ZB-5620 | 12W85 | ZT-10003 | 539187 |
| ZB 28515 | ZB-11028 | IB-1331 | 7602-0201-67 | 543435 |
| ZB8253 | ZB-10236 | IB-1330 | 7602-0201-37 | 10-6062 |
| 150TDOC8663 DC1953G6 | ZB-8662 | IB-1334 | 7602-0201-38 | 543431 |
| 24052YMW33 W45AC3 | ZB-7873 | IB-1332 | 7602-0201-47 | 549128 |
| N-2504-B | ZB-7081 | IB-657 | 7602-0200-54 | 10-6040 |
| N-2759-B | ZB-6292 | IB-675 | 7602-0200-53 | 543432 |
| Fast Change NUP464779Q4/ C9YA4 | ZB-32000 | IB-672 | 7602-0213-06 | 543433 |
| NUP464775Q4/ C9YA4 | ZB-28515 | IB-670 | 7602-0212-68 | AD4746D |
| NUP464744Q4/ C9 | ZB-26250 | IB-680 | 7602-0212-69 | ADD42605 |
| NUP464776Q4/ | ZB-25500 | IB-676 | 6319-0078-00 | AD4845D |

| | | | | |
|-----------------------|-------------------|------------|--------------|--------------|
| C9YA4 | | | | |
| NUP464777Q4/ C9YA4 | ZB-23500 | IB-671 | 7602-0212-89 | ADD42805 |
| 4G32828H | ZB-22000 | IB-678 | 6310-0012-00 | AD4746D |
| 4G32836H | ZT-16125 | IB-677 | 7602-0213-07 | AD4644D |
| 4G32840H | ZT-15000 | 12BA4 | 7602-0212-67 | AD4730D |
| 4G32844H | ZT-14500 | 12GF36 | 7602-0212-88 | ADA42207 |
| 4G32848H | ZT-13127 | 12GF38 | 7602-0211-09 | AD5140 |
| 32644H | ZT-11812 | 12GF20 | 7602-0210-37 | AD4814D |
| 154836 | ZT-10003 | 12BA6 | 7602-0213-05 | ADA426334 |
| 5G254936Q | 7602-0210-95/96) | 12W84 | 6301-0038-00 | AD5144 |
| 254941QU | 7602-0210-95/96 | 12W85 | 6397-0267-00 | AD4814D |
| 254735Q | 65-101-775 | 12BA6 | 7602-0212-90 | ADA42603 |
| 354935Q | 65-101-958 | 12BA6 | 7602-0212-91 | AD5144 |
| 5G354920Q | 65-101-954 | 12W84 | 65-725-034 | AD4812DO |
| 23160C3/W33 | IB-666/491-35 | 12W85 | 65-725-080 | AD4540D |
| 24072CA/W33 | IB-306/3693B | 12BA18 | 65-725-020 | ADA42002 |
| 24060CA/W33 | ZB-9005 | 12BA5 | 65-725-957 | AD4633D |
| 24056CA/W33 | ZB-8253 | 12AM3 | 65-725-936 | ADA42201 |
| 10929/630U | ZB-7370 | 12BA44 | 65-725-959 | AD5238X |
| 10029/630U | ZB-7120 | 12BA19 | 65-725-960 | AD4814D |
| 10129/630U | ZB-6751 | 12W73 | 65-725-000 | AD5148 |
| 10929/670U | ZB-5620 | 12W60 | 65-725-010 | MUC5136 |
| 10929/710U | ZB-11028 | 12W58 | IB-1331 | E-5140-UMR |
| 20929/530 | ZB-10236 | 12W75 | IB-1330 | MUC5144 |
| 20329/530 | ZB-8662 | 12GF20 | IB-1334 | MUC5144 |
| 20929/500 | ZB-7873 | 65-725-936 | IB-1332 | W-4482 |
| 20329/500 | ZB-7081 | 65-725-959 | IB-657 | MUC5136 |
| 229/723Q | ZB-6292 | 65-725-960 | IB-675 | X39042 |
| 92984Q | ZB-32000 | 65-725-000 | IB-672 | E5238U |
| 929/558.8Q | ZB-28515 | 65-725-010 | IB-670 | MUC5148 |
| 928/660.4Q | ZB-26250 | IB-1331 | IB-680 | ZT-7872 |
| 929/660.4Q | ZB-25500 | IB-1330 | IB-676 | ZT-8004 |
| 928/508Q | ZB-23500 | IB-1334 | IB-671 | ZT-7006 |
| 929/840U | ZB-22000 | IB-1332 | IB-677 | 7602-0220-62 |
| 228/600Q | ZT-16125 | IB-657 | 12BA4 | 7602-0220-61 |

| | | | | |
|----------------------|-----------------------------------|-----------------------------|--------------|---------------------|
| 228/666.75Q | 7602-0212-98 | IB-675 | 12GF36 | 7602-0202-01 |
| 30228/630Q | 7602-0212-98 | IB-672 | ZT-15000 | 22-030-007 |
| 2097164 | 7602-0210-93/94 | IB-670 | ZT-15000 | IB-666 |
| 2097172 | 7602-0210-95/96 | IB-680 | ZT-14500 | IB-429 |
| 97860 | 65-101-775 | IB-676 | ZT-13127 | IB-411 |
| 97960 | 65-101-958 | IB-671 | ZT-11812 | 4600170/6493 66 |
| 4G32836H5691 /600 | 65-101-954 | IB-677 | ZT-10003 | 4600169/6494 72 |
| 5691/500 | IB-666/491-35 | 12BA4 | 7602-0201-67 | ZA-6870 |
| 5691/630 | IB-306/3693B | 12GF36 | 7602-0201-37 | 7602-0210-67 |
| 1689/520 | ZB-9005 | 12GF38 | 7602-0201-38 | 7602-0212-98 |
| 1689/620 | ZB-8253 | 12GF20 | 7602-0201-47 | 7602-0210-93/ 94 |
| 1687/560 | ZB-7370 | 12BA4 bearing(original) | 7602-0200-54 | 7602-0210-95/ 96 |
| 1687/650 | ZB-7120 | 12BA4 | 7602-0200-53 | 65-101-775 |
| 1687/810 | ZB-6751 | 12GF36 | 7602-0213-06 | 65-101-958 |
| 1681/800 | ZB-5620 | 12GF38 | 7602-0212-68 | 65-101-954 |
| 5692/800 | ZB-11028 | 12GF20 | 7602-0212-69 | IB-666/491-35 |
| 2687/1049 | ZB-10236 | 12BA6 | 6319-0078-00 | IB-306/3693B |
| 38780 | ZB-8662 | 12W84 | 7602-0212-89 | ZB-9005 |
| 5691/750 | ZB-7873 | 12W85 | 6310-0012-00 | ZB-8253 |
| 5691/600 | ZB-7081 | 12BA18 | 7602-0213-07 | ZB-7370 |
| 5691/500 | ZB-6292 | 12BA5 | 7602-0212-67 | ZB-7120 |
| 569196 | ZB-32000 | 12AM3 | 7602-0212-88 | ZB-6751 |
| 569184 | ZB-28515 | 12BA44 | 7602-0211-09 | ZB-5620 |
| 569164 | ZB-26250 | 12BA19 | 7602-0210-37 | ZB-11028 |
| 1689/520 | ZB-25500 | 12W73 | 7602-0213-05 | ZB-10236 |
| 1689/620 | ZB-23500 | 12W60 | 6301-0038-00 | ZB-8662 |
| 1687/560 | ZB-22000 | 12W58 | 6397-0267-00 | ZB-7873 |
| 1687/560K1 | 7602-0210-67 bearing(original) | IB-676 bearing(original) | 7602-0212-90 | ZB-7081 |
| 1687/562K2 | 7602-0210-67 | IB-676 | 7602-0212-91 | ZB-6292 |
| 1687/650 | 7602-0212-98 | IB-671 | 65-725-034 | ZB-32000 |
| 1687/770 | 7602-0210-93/94 | IB-677 | 65-725-080 | ZB-28515 |

| | | | | |
|-------------|-----------------------------|-----------------------------|-------------------------------|--------------|
| 5692/530 | 7602-0210-95/96 | 12BA4 | 65-725-020 | ZB-26250 |
| | 65-101-775 | 12GF36 | 65-725-957 | ZB-25500 |
| | 65-101-958 | 12GF38 | 65-725-936 | ZB-23500 |
| 5692/630 | 65-101-954 | 12GF20 | 65-725-959 | ZB-22000 |
| 5692/670 | IB-666/491-35 | 12BA6 | 65-725-960 | ZT-16125 |
| 5692/800 | IB-306/3693B | 12W84 | 65-725-000 | ZT-15000 |
| 2687/1049 | ZB-9005 | 12W85 | 65-725-010 | ZT-14500 |
| 2327/1049YA | ZB-8253 | 12BA18 | IB-1331 | ZT-13127 |
| 37941K | ZB-7370 | 12BA5 | IB-1330 | ZT-11812 |
| 37951K | ZB-7120 | 12AM3 | IB-1334 | ZT-10003 |
| 39761K | ZB-6751 | IB-670 bearing(original) | IB-1332 | 7602-0201-67 |
| 2097938K | ZB-5620 | IB-670 | IB-657 | 7602-0201-37 |
| 2097948K | ZB-11028 | IB-680 | IB-675 | 7602-0201-38 |
| 2097952K | ZB-10236 | IB-676 | IB-672 | 7602-0201-47 |
| 9549436K | ZB-8662 | IB-671 | IB-670 | 7602-0200-54 |
| T661T611 | ZB-7873 | IB-677 | IB-680 | 7602-0200-53 |
| T691 | ZB-7081 | 12BA4 | IB-676 | 7602-0213-06 |
| T911 | ZB-6292 | 12GF36 | IB-671 | 7602-0212-68 |
| T911A | ZB-32000 | 12GF38 | IB-678 | 7602-0212-69 |
| 9836 | ZB-28515 | 12GF20 | ZB-25500 bearing(original) | 6319-0078-00 |
| 9840 | ZB-26250 | 12BA6 | ZB-25500 | 7602-0212-89 |
| 98/500 | ZB-25500 | 12W84 | ZB-23500 | 6310-0012-00 |
| 7549436Q | ZB-23500 | 12W85 | ZB-22000 | 7602-0213-07 |
| 99434Q4 | ZB-22000 | 12BA18 | ZT-16125 | 7602-0212-67 |
| 99436Q4 | IB-411 bearing(original) | 12BA5 | ZT-15000 | 7602-0212-88 |
| 99456Q4 | IB-411 | 12AM3 | ZT-14500 | 7602-0211-09 |
| 91754 | 4600170/649366 | 12BA44 | ZT-13127 | 7602-0210-37 |
| 19954EQ | 4600169/649472 | 12BA19 | ZT-11812 | 7602-0213-05 |
| 549832K | ZA-6870 | 12W73 | ZT-10003 | 6301-0038-00 |
| 3-939 | 7602-0210-67 | 12W60 | 7602-0201-67 | 6397-0267-00 |
| 549744 | 7602-0212-98 | 12W58 | 7602-0201-37 | 7602-0212-90 |
| 549822 | 7602-0210-93/94 | IB-675 bearing(original) | 7602-0201-38 | 7602-0212-91 |

| | | | | |
|--------------|-----------------|--------|--------------|------------|
| 811/500M | 7602-0210-95/96 | IB-675 | 7602-0201-47 | 65-725-034 |
| 811/530M | 65-101-775 | IB-672 | 7602-0200-54 | 65-725-080 |
| 811/560M | 65-101-958 | IB-670 | 7602-0200-53 | 65-725-020 |
| 817/600M | 65-101-954 | IB-680 | 7602-0213-06 | 65-725-957 |
| 75492/670 | IB-666/491-35 | IB-676 | 7602-0212-68 | 65-725-936 |
| 75491/900 | IB-306/3693B | IB-671 | 7602-0212-69 | 65-725-959 |
| 4G32836H | ZB-9005 | IB-677 | 6319-0078-00 | 65-725-960 |
| 602-0220-62 | ZB-8253 | 12BA4 | 7602-0212-89 | 65-725-000 |
| 7602-0220-61 | ZB-7370 | 12GF36 | 6310-0012-00 | 65-725-010 |
| 7602-0202-01 | ZB-7120 | 12GF38 | 7602-0213-07 | IB-1331 |
| 22-030-007 | ZB-6751 | 12GF20 | 7602-0212-67 | IB-1330 |

Pls contact us freely if you have any need of bearings,seals,pillow block or other accessories.

We will quote you our favorable price promptly.

Online Chat Support

If you need any assistance or have any questions you would like help with then why not talk live with one of our operators.

Our experienced operators can assist you in making the right choice!

